


ARTEMIS Case Study



Situation

- 10" WI "Unpiggable" Flowline
- 5 areas selected for inspection of corrosion/erosion rate since previous inspection
- 4 mm Polyethylene and FBE coating
- Partially buried





Onshore Blind Testing

All 7 defects found with high degree of accuracy



Results

- All defects found with high accuracy
- No coating removal required
- Minimal dredging required, saving several days vessel time
- Inspection speed was 30% of allocated operator time

"ARTEMIS® provided data as good and faster as other methods I've used. This allowed us to reduce the amount of dredging which saved us a significant amount of time and money"

Client Name Redacted



www.tscsubsea.com